



737NG – ATA 78

Possible Long Primary Exhaust Nozzle Departure Due to Fan Blade Failure

Presenter: Ying Zhao – Propulsion Service Engineer

737NG/MAX Fleet Team Meeting, May 5-7, 2020

Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.

Panel Members

Name	Organization
Patrick Foy	Boeing Nacelle Structures Engineering Unit Member

Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.

737NG – ATA 78

Possible Long Primary Exhaust Nozzle Departure Due to Fan Blade Failure

Affected Models: 737NG with long (pre-PIP) primary exhaust nozzles

(aircraft prior to LN 3762)

Part Numbers: 314A2610-1/-62/-68

SRP: 737NG-SRP-78-0110

FIX: ISS-78-20-30510

FTD: 737NG-FTD-78-20001



Issue/Background

- Two in-flight fan blade failure events resulted in damage to the primary exhaust nozzle structures. Nacelle structural components also departed the aircraft (parts of the inlet on both events, and parts of the fan cowl on one event).
 - August 27, 2016, a Boeing 737-700 experienced a left engine fan blade failure while climbing to flight altitude.
 - April 17, 2018, a Boeing 737-700 experienced a left engine fan blade failure while climbing to flight altitude.
- Departure of long (pre-PIP) primary exhaust nozzle is possible in combination with a fan blade failure event.
- This issue only affects 737NG with long (pre-PIP) primary exhaust nozzles, Part Numbers: 314A2610-1/-62/-68. This configuration was delivered on aircraft prior to LN 3762.

Root Cause

- Boeing is currently undergoing root cause investigation and analysis.

Interim/Mitigating Action

- The regulatory agencies issued airworthiness directive (AD) mandated inspections of the engine fan blades (FAA AD 2018-09-51, FAA AD 2018-09-10, EASA AD 2019-0018).

Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.

737NG – ATA 78

Possible Long Primary Exhaust Nozzle Departure Due to Fan Blade Failure

Background

- This issue only affects 737NG with long pre-PIP primary exhaust nozzles, **Part Numbers: 314A2610-1/-62/-68.**
- Figures show the Engine 1 primary nozzle exhaust damages from the 2016 event.
- The primary exhaust nozzle exhibited 360° circumferential buckling and still remained attached to the engine.



Figure 1: Front View of Engine 1



Figure 2: Right Side of Engine 1



Figure 3: Lower View of Right Side of Engine 1

737NG – ATA 78

Possible Long Primary Exhaust Nozzle Departure Due to Fan Blade Failure

Background

- Figures show the Engine 1 primary nozzle exhaust damages from the 2018 event.
- The primary exhaust nozzle exhibited 360° circumferential buckling, was torn continuous from the 5:00 to 12:30 o'clock position and still remained attached to the engine.
- The nozzle also exhibited tears of about 1.00-inches at 1:00, 3:00, 4:00, and 4:40 o'clock positions.



Figure 4: Left Side of Engine 1



Figure 5: Right Side of Engine 1

Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.

737NG – ATA 78

Possible Long Primary Exhaust Nozzle Departure Due to Fan Blade Failure

Final Action/Resolution


- TBD

Regulatory Action/Activity

- Boeing understands that the FAA is reviewing this issue for possible regulatory action. We will advise further on this as soon as more information becomes available.

Status

- Boeing is actively working to determine root cause.
- The fleet will be kept informed of status via 737NG-FTD-78-20001 and fleet team calls/meetings.



Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.



Questions?





Back Up Slides


Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.

737NG – ATA 78


Possible Long Primary Exhaust Nozzle Departure Due to Fan Blade Failure

737NG Exhaust Nozzle Delivery Configuration Overview

Long Nozzle Configuration



PIP Exhaust Nozzle



314A2610 (EIS)
(-1, -62, -68)

Long Nozzle

Line #s:
1-3611, 3613-3701, 3703-3761

(A/Ps = ~3750) **Units: ~7500**

314A2630 (PIP)
(-100 to -105)

PIP Nozzle with honeycomb acoustic liner

Line #s:
3612, 3702 &
3762 and on
1st Del= 9/06/2011
PRR 38918

(A/Ps = ~3330) **Units: ~6660**

Proprietary: The information contained herein is proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part except when such user possesses direct, written authorization from The Boeing Company. The statements contained herein are based on good faith assumptions and are to be used for general information purposes only. These statements do not constitute an offer, promise, warranty or guarantee of performance.