关于 NG 和 MAX 飞机着陆转弯灯不亮排故手册差异的维护提示							
编号	编写人	审核人		日期			
KMYS-2023-20	朱红洲	朱红洲	20	2023-10-17			
一、背景							
NG 飞机和 MAX 飞机自	n LED 着陆灯和转	弯灯组件件号相	同,但其:	排故手	- 册确不		
同,如果按NG飞机得	·习惯去办理 MAX 的	1着陆灯和转弯灯	故障保留	时, 豆	「能会出		
现不符合手册的情况。	0						
二、依据文件							
IPC, FIM, IFIM							
三、系统描述							
NA NA							
四、内容							
1、NG 飞机 LED 着陆州	了和转弯灯件号 ·						
30 72500410-2	ROLL, AND TAKEO ELECTRICAL EQUIP N L01543 QUALIFIED I/W DATA: 72500454-002 CAI REPLACED BY 72	MANUAL REF: IPTION: INTENSITY OR AIRCRAFT CHDOWN, GROUND OFF NUMBER: N REPLACE OR BE 500410-2 ONLY FOR	099-100, 102-193, 197-198, 204-700, 711-721, 837-837, 846-852, 854-999	1	AR		
	REPLACED SIMU	2500410-2 MUST BE					

ALONGSIDE THE LTRTL MAIN ARRAY ASSY (LH OUTBOARD) P/N 72500410-1.

	25	72500415-1	•LIGHT ASSY - RUNWAY TURN OFF Supplier Code: V72914 COMPONENT MAINT MANUAL REF: 33-43-88 FUNCTIONAL DESCRIPTION: RUNWAY TURNOFF LIGHTS SHINE TO THE SIDE OF THE AIRPLANE TO ILLUMINATE RUNWAY EDGES AND TURNOFFS AND TO PROVIDE GROUND ILLUMINATION WHEN THE AIRPLANE IS TURNING	099-100, 102-193, 197-198, 204-700, 711-721, 837-837, 846-852, 854-999	1	AR
	85	72500460-001	•LIGHT ASSY - RUNWAY TURN OFF Supplier Code: V72914 COMPONENT MAINT MANUAL REF: 33-43-89 POSITION DATA: LH SIDE FUNCTIONAL DESCRIPTION: RUNWAY TURNOFF LIGHTS SHINE TO THE SIDE OF THE AIRPLANE TO ILLUMINATE RUNWAY EDGES AND TURNOFFS AND TO PROVIDE GROUND ILLUMINATION WHEN THE AIRPLANE IS TURNING	099-100, 102-193, 197-198, 204-700, 711-721, 837-837, 846-852, 854-999	1	AR
2.	MAX	飞机 LED 着陆》	汀和转弯灯件号			
	30	72500410-2	• ARRAY ASSY - LED (ESDS)	001-999	1	AR
			Supplier Code: V72914			
			COMPONENT MAINT MANUAL REF: 33-43-91			
			POSITION DATA: LH INBD			
			FUNCTIONAL DESCRIPTION: PROVIDES HIGH INTENSITY ILLUMINATION FOR AIRCRAFT APPROACH, TOUCHDOWN, GROUND ROLL, AND TAKEOFF			
			ELECTRICAL EQUIP NUMBER: L01543			
			QUALIFIED I/W DATA: 72500454-002 CAN REPLACE OR BE REPLACED BY 72500410-2 ONLY FOR THE LTRTL MAIN ARRAY ASSY (LH INBOARD) P/N 72500410-2 MUST BE REPLACED SIMULTANEOUSLY ALONGSIDE THE LTRTL MAIN ARRAY ASSY (LH OUTBOARD) P/N 72500410-1.			

	25	72500415-1	•LIGHT ASSY	001-999	1	AR
			Supplier Code: V72914			
			COMPONENT MAINT MANUAL REF: 33-43-88			
			POSITION DATA: LH SIDE			
			FUNCTIONAL DESCRIPTION: RUNWAY TURNOFF LIGHTS SHINE TO THE SIDE OF THE AIRPLANE TO ILLUMINATE RUNWAY EDGES AND TURNOFFS AND TO PROVIDE GROUND ILLUMINATION WHEN THE AIRPLANE IS TURNING			
			ELECTRICAL EQUIP NUMBER: L01545			
	100	72500460-001	•LIGHT ASSY	001-999	1	AR
			Supplier Code: V72914			
			COMPONENT MAINT MANUAL REF: 33-43-89			
			POSITION DATA: LH SIDE			
			FUNCTIONAL DESCRIPTION: RUNWAY TURNOFF LIGHTS SHINE TO THE SIDE OF THE AIRPLANE TO ILLUMINATE RUNWAY EDGES AND TURNOFFS AND TO PROVIDE GROUND ILLUMINATION WHEN THE AIRPLANE IS TURNING			
			ELECTRICAL EQUIP NUMBER: L01545			
			FUNCTIONAL REFERENCE: PLACARDS AND MARKINGS FOR DETAILS SEE: 11-24-04-54			

从上文1和2可以看出,NG和MAX飞机的着陆灯和转弯灯组件件号一样。

- 3、NG 飞机 FIM TASK 33-40 TASK 803 LED Landing and Runway Turnoff Lights
- Fault Isolation

- E. Fault Isolation Procedure Inboard Array, Outboard Array or Runway Turnoff Light (RTO) Does Not Come On
 - If the power supply (PS) OK indicator is ON;

NOTE: The PS OK indicator is a blue LED located on the RTO light assembly.

- (a) Replace the non-working array(s) or RTO.
- (b) If the light comes on, then you corrected the fault.
- (2) If the power supply (PS) OK indicator is OFF;

NOTE: The PS OK indicator is a blue LED located on the RTO light assembly.

- (a) Replace the non-working arrays(s) or RTO.
- (b) If the light comes on, then you corrected the fault.
- (c) If the light does not come on, then continue.
- (d) Do a continuity check of the wire bundle between the power supply and the non-working array(s) or RTO.
- 4、MAX 飞机 IFIM 33-10-00-810-809 Wing landing lights do not operate correctly left.
- B. Initial Evaluation
 - (1) For the left landing and taxi light main array, do the Installation Test part of this task:
 - Fixed Landing Light Main Array Assembly Replacement, AMM TASK 33-42-21-960-801.
 - (a) If the system does not operate as specified in the AMM task, then do the Fault Isolation Procedure below.
 - (b) If the system operates as specified in the AMM task, then there was an intermittent fault.
- C. Fault Isolation Procedure
 - (1) Do this check of the voltage at the left LTRTL power supply:
 - (a) Disconnect connector D15948 from the left LTRTL power supply, M3079.
 - (b) Do a check for voltage between pin 4 and pin 7 of connector D15948 (WDM 33-42-21). The correct voltage is 115 VAC.
 - (c) If the correct voltage is not present, then do this check of the wiring:
- 5、MAX 飞机 IFIM 33-40-00-810-804 Runway turnoff light does not operate correctly left.

B. Initial Evaluation

- (1) Monitor the left LTRTL RTO light while you do the next step.
- (2) Set the RUNWAY TURNOFF L switch (flight deck) to ON, and then set it to OFF.
- (3) If the left LTRTL RTO light did not operate correctly at each switch position, then do the Fault Isolation Procedure below.
- (4) If the left LTRTL RTO light operated correctly at each switch position, then there was an intermittent fault.

C. Fault Isolation Procedure

- (1) Replace the left LTRTL RTO light, L1545. This is the task:
 - Runway Turnoff Light Light Assembly Replacement, AMM TASK 33-42-21-960-803.
 - (a) Set the RUNWAY TURNOFF L switch (flight deck) to ON, and then set it to OFF.
 - (b) If the left LTRTL RTO light operated correctly at each switch position, then you corrected the fault.
 - (c) If the left LTRTL RTO light did not operate correctly at each switch position, then continue.
- (2) Do this check of the voltage at the left LTRTL power supply:
 - (a) Disconnect connector D15948 from the left LTRTL power supply, M3079.

从3、4、5可以看出,NG飞机FIM中可以通过PS (power supply)指示灯判断故障,而MAX飞机IFIM中并未提及,尽管其件号相同。

总结: 在判断故障时,尽可能通过串件、量线确定故障源,避免因相同的故障 现象而故障源不同造成判断不准确。