



We found hanging down condition of No.6 flap track fairing with the Flap in the Up position.




Figure 1 - JA05RK\_Worn Damage – Lower Bearing Thread of No.6 Flap Track Fairing Drive Rod



Figure 1 - JA05RK\_Worn Damage – Lower Bearing Thread of No.6 Flap Track Fairing Drive Rod

During our 737-800 fleet inspection of JA03RK, the locknut(P/N: NAS509L6C or BACN11U6CM1L) loose condition of drive rod assy was found in No. 6 flap track fairing.





Figure 2 - Locknut Loose Condition of No.6 Flap Track Fairing on JA03RK

Detail "B"




Figure 2 - Locknut Loose Condition of No.6 Flap Track Fairing on JA03RK