

737 MAX Fan Cowl Latch Indication System (LIS)

External View Latch #2





BOEING PROPRIETARY

External View OTAD




Stowed Handle with OTAD closed



Deployed Handle preventing OTAD from closing

737 MAX Fan Cowl Latch Indication System (LIS)





BOEING PROPRIETARY