

737 No.2 Window - Assembly and Window Frame Opening

Ideal Condition vs Non-Ideal Condition

Clean Drain Holes in Window Frame Assembly:



Clogged Drain Hole In Window Frame Assembly:



Clean Drain Holes in Window Sill (Structure):



Clogged Drain Holes in Window Sill (Structure):



Clean Terminals, Ruber Boots Installed and Not Damaged:



Dirty Terminals:

